


Carl L. Newman  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N. Y. 10003  
Telephone (212) 460-5133



January 20, 1975

Re Indian Point Unit No. 2  
AEC Docket No. 50-247

Mr. George Lear, Chief  
Operating Reactor Branch #3  
Directorate of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Lear

In response to your letter of December 18, 1974, we are presently re-investigating the possible failure of non-Category I equipment which could adversely affect the performance of safety-related equipment required for safe shutdown of the facility or to limit the consequences of a potential accident.

In response to a September 26, 1972 letter from the Regulatory Staff (Mr. DeYoung to Mr. William J. Cahill, Jr.), a similar analysis was performed. Our letter of December 18, 1972, outlined the protective measures which we proposed to take. These measures included installing redundant level alarms in the common Turbine Hall for Indian Point Units 1 and 2, and modifying a number of doors in the plant to assure that adequate drainage of the enclosed rooms could be achieved. These modifications have since been implemented, and no further actions are presently believed to be necessary.


We are reviewing the previous analysis in light of your December 18, 1974 letter and as you have requested, we will submit the results within sixty days following the date of your letter.

Very truly yours

*Carl L. Newman*

Carl L. Newman  
Vice President

mk



8111090363 750120  
PDR ADOCK 05000247  
P PDR

Regulatory

File Cy.

756

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 756

FILE: INCIDENT REPORT

FROM: Con. Edison Co. of NY New York, NY 10003 Carl Newman		DATE OF DOC 1/20/75	DATE REC'D 1/23/75	LTR XX	TWX	RPT	OTHER
TO: George Lear		ORIG 1 signed	CC	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XX	PROP INFO	INPUT	NO CYS REC'D 1 signed	DOCKET NO: 50-247		

DESCRIPTION:

Ltr responding to our 12/18/74 ltr re: the possible failure of non-Category I equipment which could affect the performance of safety-related equipment

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Indian Point Unit 2

FOR ACTION/INFORMATION LDM 1/20/75

BUTLER (S)	SCHWENCER (S)	ZIEMANN (S)	REGAN (E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK (S)	STOLZ (S)	DICKER (E)	✓ LEAR (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (S)	VASSALLO (S)	KNIGHTON (E)	SPEIS (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (S)	PURPLE (S)	YOUNGBLOOD (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC. ASST.</u>	<u>A/T IND</u>
✓ AEC PDR	✓ SCHROEDER	GRIMES	DIGGS (S)	BRAITMAN
✓ OGC, ROOM P-506-A	✓ MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
✓ MUNTZING/STAFF	✓ KNIGHT	✓ KASTNER	GOULBOURNE (S)	B. HURT
✓ CASE	✓ PAWLICKI	BALLARD	KREUTZER (E)	
GIAMBUSSO	✓ SHAO	SPANGLER	LEE (S)	<u>PLANS</u>
BOYD	✓ STELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	✓ HOUSTON	<u>ENVIRO</u>	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	✓ NOVAK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	✓ CROSS	DICKER	SHEPPARD (S)	E. COUPE
GOLLER (S)	✓ IPPOLITO	KNIGHTON	SLATER (E)	✓ R. Hartfield (2)
P. COLLINS	TEDESCO	YOUNGBLOOD	SMITH (S)	✓ KLECKER
DENISE	✓ LONG	REGAN	✓ TEETS (S)	✓ F. WILLIAMS
<u>REG OPR</u>	✓ LAINAS	PROJECT LDR	WILLIAMS (E)	
✓ FILE & REGION	✓ BENAROYA		WILSON (S)	
✓ T.R. WILSON	✓ STEELE	✓ VOLIMER	INGRAM (S)	
		HARLESS		

EXTERNAL DISTRIBUTION

✓ 1-LOCAL PDR Nontrose, NY	(1) (2) (10) - NATIONAL LABS	1-PDR SAN/LA/NY
✓ 1-TIC (ABERNATHY)	1-M. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
✓ 1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRINSON, ORNL
1-ASLB	NEWMARK/BLUME/AGBABIAN	1-AGMED (RUTH GUSSMAN)
1-NEWTON ANDERSON		RM B-127 G.T.
✓ 5-ACRS SENT TO LIC. ASST.		1-J. RUNKLES, RM E-201
		G.T.

Teets 1-24-75