Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y 10003 Telephone (212) 460-3819

## **REGULATORY DOCKET FILE COPY**

November 18, 1977

Re: Indian Point Unit Nos. 2 & 3 Docket Nos. 50

Director of Nuclear Reactor Regulation ATTN: Mr. Robert W. Reid, Chief Operating Reactors Branch No. 4 Division of Operating Reactors U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Reid:

By letters dated September 14, 1977 and October 27, 1977, you requested certain information regarding the fracture toughness and potential for lamellar tearing of the Indian Point Unit Nos. 2 & 3 steam generator and reactor coolant pump support materials.

Accordingly, our NSSS vendor is presently assembling the plant design data necessary to properly respond to your request. This compilation of plant data is presently scheduled for completion and transmittal to Con Edison by February 1, 1978. Therefore, it is now anticipated that responses to your questions can be provided no later than March 1, 1978.

Very truly yours,

William J. Cahill, Jr. Vice President

cc: Mr. George T. Berry General Manager and Chief Engineer Power Authority of the State of New York 10 Columbus Circle New York, N. Y. 10019



Aces Sectio