

William J. Cahill, Jr.  
Vice President


Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

May 19, 1977

Re: Indian Point Units No. 2 and 3  
Docket Nos. 50-247 and 40-286

## Regulatory Docket File

Director of Nuclear Reactor Regulation  
ATTN: Mr. Robert W. Reid, Chief  
Operating Reactors Branch #4  
Division of Operating Reactors  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555




Dear Sir:

In response to your letter of March 28, 1977, we have reviewed the diesel generator alarm and control circuitry at Indian Point Units No. 2 and 3. Attachment I to this letter provides answers to the questions raised in your letter. We are planning to install the modification proposed in our response to your question (e) at future shutdowns of sufficient duration.

Should you or your staff have any further questions, we would be pleased to discuss them with you.

Sincerely,

  
William J. Cahill, Jr.  
Vice President

Attachment

CC: Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

8111230356 770519  
PDR ADDCK 05000247  
PDR