

Charles W. Jackson
Vice President

POR

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Rensselaer Ave.
Buchanan, NY 10511
Telephone (914) 737-8116

May 11, 1981

Re: Indian Point Unit No. 2
Docket No. 50-247



Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Grier:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms notification to Mr. T. Kenny of your office, by Mr. C. Jackson of Consolidated Edison, of a potential Reportable Occurrence LER 81-012/1. This event is the type defined in Technical Specification Section 6.9.1.7.1 (c).

While conducting testing to assure operability of the LPI/RHR check valves prior to plant restart, a 3/4" swagelok union in the remote reactor head vent line parted. At the time of this event the reactor coolant system temperature and pressure were approximately 320F and 1200 psig respectively. The leakage was simultaneously identified by the control room operators and a technician who was in the containment at the time and was promptly terminated by closing the reactor head vent isolation valve.

Consolidated Edison believes that this report also satisfies the requirements of 10CFR Part 21.

Very truly yours,

A handwritten signature in dark ink, appearing to read "Charles W. Jackson".

Charles W. Jackson
Vice President
Nuclear Power

CWJ/hm

cc: Mr. William McDonald, Director (2 copies)
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. T. Rebelowski, Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 28
Buchanan, New York 10511

8106040268 S

A002
5/11

