

December 29, 2009

Raymond S. Sterman, Chairman
Prime Technology, LLC
344 Twin Lakes Road
North Branford, CT 06471

SUBJECT: PRIME TECHNOLOGY RESPONSE TO NRC INSPECTION REPORT
99901382/2009-201, NOTICE OF VIOLATION, AND NOTICE OF
NONCONFORMANCE

Dear Mr. Sterman:

Thank you for your letter dated November 30, 2009, in response to the Notice of Violation (NOV) and Notice of Nonconformance (NON) that were discussed in the U.S. Nuclear Regulatory Commission (NRC) Inspection Report 99901382/2009-201 dated September 24, 2009.

We have reviewed your letter and find it responsive to the NOV's and NON's documented in Inspection Report 99901382/2009-201. At this time we have no further questions or comments, and find that your response to Inspection Report 99901382/2009-201 addressed the identified issues. However, the breadth of findings indicated weaknesses throughout the areas of inspection. As a result, we expect to conduct a follow-up inspection within a year to review the implementation of your corrective actions and to determine compliance has been achieved and is being maintained.

If you or your staff has any questions regarding this matter, we will be pleased to discuss them with you. Please contact Ms. Carla Roquecruz at (301) 415-1455 or via electronic mail at Carla.Roquecruz@nrc.gov, if you have any questions or need assistance regarding this matter.

Sincerely,

Patrick L. Hiland, Director /RA/
Division of Engineering
Office of Nuclear Reactor Regulation

Docket No. 99901382

December 29, 2009

Raymond S. Sterman, Chairman
Prime Technology, LLC
344 Twin Lakes Road
North Branford, CT 06471

SUBJECT: PRIME TECHNOLOGY RESPONSE TO NRC INSPECTION REPORT
99901382/2009-201, NOTICE OF VIOLATION, AND NOTICE OF
NONCONFORMANCE

Dear Mr. Sterman:

Thank you for your letter dated November 30, 2009, in response to the Notice of Violation (NOV) and Notice of Nonconformance (NON) that were discussed in the U.S. Nuclear Regulatory Commission (NRC) Inspection Report 99901382/2009-201 dated September 24, 2009.

We have reviewed your letter and find it responsive to the NOV's and NON's documented in Inspection Report 99901382/2009-201. At this time we have no further questions or comments, and find that your response to Inspection Report 99901382/2009-201 addressed the identified issues. However, the breadth of findings indicated weaknesses throughout the areas of inspection. As a result, we expect to conduct a follow-up inspection within a year to review the implementation of your corrective actions and to determine compliance has been achieved and is being maintained.

If you or your staff has any questions regarding this matter, we will be pleased to discuss them with you. Please contact Ms. Carla Roquecruz at (301) 415-1455 or via electronic mail at Carla.Roquecruz@nrc.gov, if you have any questions or need assistance regarding this matter.

Sincerely,

Patrick L. Hiland, Director */RA/*
Division of Engineering
Office of Nuclear Reactor Regulation

Docket No. 99901382

DISTRIBUTION:

ADAMS Accession No.: ML093630015

OFFICE	NRR/DE/EQVB	NRR/DE/EQVB	NRR/DE/EQVB	NRR/DE
NAME	AArmstrong	C Roquecruz	DThatcher	PHiland
DATE	12/ 23 /2009	12/ 23 /2009	12/ 23 /2009	12/ 28 /2009

OFFICIAL RECORD COPY