

NOV 10 1970

Peter A. Morris, Director
Division of Reactor Licensing

CONSOLIDATED EDISON - INDIAN POINT NO. 2 - DOCKET NO. 50-247

The information submitted by the applicant in the FSAR with respect to the operating limitations imposed by the fracture toughness properties of the materials of the Indian Point 2 reactor vessel has been reviewed and evaluated by the DRS Mechanical Engineering Branch. An evaluation of this information and our recommendation concerning operating limits appropriate for inclusion in the applicant's Technical Specifications are enclosed.

Original signed by,
E. G. Case

Edson G. Case, Director
Division of Reactor Standards

DRS 50-247

Enclosure:
Indian Point 2 Report

cc w/encl.
S. Hanauer, DR
R. Boyd, DRL
D. Skovholt, DRL
R. DeYoung, DRL
R. Maccary, DRS
S. Pawlicki, DRS
D. Muller, DRL
K. Kniel, DRL

8111140220 701110
ADOCK 05000247

OFFICE ▶	DRS:MEB	DRS:AD/E	DRS:DIR			
SURNAME ▶	SPawlicki:amp	RMaccary	EGCase			<i>mmu</i>
DATE ▶	11/9/70	11/9/70	11/9/70			