

T. F. Engelhardt, GC

March 15, 1968

THRU: R. S. Boyd, A/D, RP, DRL

THRU: D. R. Muller, Chief, RPB-1, DRL

Karl Kniel, Project Leader

Reactor Project Branch #1, DRL

LIST OF REFERENCES TO REACTOR PIT CRUCIBLE FOR
CONSOLIDATED EDISON'S INDIAN POINT STATION NO. 2, DOCKET NO. 50-247

Date	Document	Page No.
July 28, 1966	Fifth Supplement to Preliminary Safety Analysis Report	p. 2-1 to 2-10
Aug. 3, 1966	USAEC Division of Reactor Licensing Report to ACRS in the matter of Indian Point Unit No. 2, Report No. 4	p. 9 to 13
Aug. 16, 1966	ACRS Letter on Indian Point 2	p. 2
Aug. 25, 1966	Safety Evaluation by the Division of Reactor Licensing, USAEC, for Indian Point 2	p. 69*
Sept. 1966	Proceedings of the Indian Point Unit No. 2 Public Hearing	
Oct. 16, 1967	Seventh Supplement to Preliminary Safety Analysis Report	p. 7-1 to 7-12
Feb. 23, 1968	USAEC Division of Reactor Licensing Report to ACRS in the matter of Indian Point Unit No. 2	p. 26 to 28

* There appears to be no direct reference to the crucible in this report. Under R&D on p. 69, Item 3 is "Research of Consequences of Failure of Core Cooling Systems and Development of Means to Ameliorate the Consequences."

Distribution:

Suppl. 

DRL Reading

RPB-1 Reading

R. S. Boyd

D. R. Muller

Karl Kniel

8111230111 680315
ADOCK 05000247

Original Signed by
D. R. Muller

OFFICE	DRL:RPB-1	DRL:RPB-1	DRL:RP		
SURNAME	KKniel/eb	DRMuller	RSBoyd		
DATE	3/15/68	3/15/68	3/15/68		