

MAR 20 1974

E. J. Brunner, Chief
Facility Test and Startup Branch
Directorate of Regulatory Operations
Region I

LOSS OF INSTRUMENT AIR, INDIAN POINT UNIT 2 - DOCKET NO. 50-247

In reply to your memo (not dated) of approximately October 1, 1973 requesting information regarding the evaluation of the potential loss of both instrument air sources we are enclosing a copy of a memo from K. V. Seyfrit to H. D. Thornburg dated March 13, 1974.

Original signed by
H.D. Thornburg

Harold D. Thornburg, Chief
Field Support & Enforcement Branch
Directorate of Regulatory Operations

Enclosure:
As stated

8111140565 740320
ADOCK 05000247

OFFICE	RO:FS/EB	RO:FS/EB,C				
SURNAME	FADreher:gas	H.D. Thornburg				
DATE	3/19/74	3-14-74				