

FEB 8 1968

Distribution:  
Suppl. ←  
DRL Reading  
RPB-1 Reading  
R. S. Boyd  
D. R. Muller  
N. M. Blunt (2)

Docket No. 50-247

Dr. Carroll W. Zabel  
Chairman, Advisory Committee  
on Reactor Safeguards  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Dr. Zabel:

Transmitted for the information of the Committee are three  
copies of the following:

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.  
(Indian Point Nuclear Generating Station Unit No. 2)

Informal report, dated January 1968, prepared by the  
above Company, on the Containment Building Liner  
Plate Buckle in the Vicinity of the Fuel Transfer  
Canal of the Indian Point Nuclear Generating Station,  
Unit No. 2.

Sincerely yours,

Original Signed by  
D. R. Muller

Peter A. Morris, Director  
Division of Reactor Licensing

Enclosures:  
As stated above (3)

8111230028 680223  
PDR ADOCK 05000247  
A PDR



OFFICE ▶	DRL:RPB-1	DRL:RPB-1	DRL:RPB-1			
SURNAME ▶	NMBlunt:brm <i>brm</i>	KKniel <i>KK</i>	DRMuller <i>DM</i>			
DATE ▶	2/7/68	2/8/68	2/8/68			