



UNITED STATES
ATOMIC ENERGY COMMISSION

WASHINGTON, D.C. 20545

FEB 5 1974

Richard Webb
University of Indiana
1026 E. 3rd Street
Bloomington, Indiana 47401

Dear Mr. Webb:

In reply to your telephone request enclosed are copies of the following reports on the Consolidated Edison Company of New York (Indian Point 2) "Failure of a 18 inch Feedwater Line to the Steam Generator" incident:

1. Consolidated Edison Company initial report of the incident dated November 30, 1973.
2. USAEC Regulatory Operations, Region I Report No. 50-247/73-23 dated December 5, 1973.

The final report from Consolidated Edison Company or the Regulatory Operations, Region I Office has not been received to date.

Harold D. Thornburg
Harold D. Thornburg, Chief
Field Support & Enforcement Branch
Directorate of Regulatory Operations

Enclosure:
As stated

8111180669 740903
PDR ADOCK 05000247
S PDR