

Docket No. 50-247

JUN 13 1972

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Dr. Siess:

Sixteen copies of the following are transmitted for the information of the Committee:

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.
(Indian Point Nuclear Generating Unit No. 2)

Letter, dated June 7, 1972, from Consolidated Edison Company of New York, Inc., and a Westinghouse report entitled, "A Technical Report on Steam Generator Tubesheet Cladding," Part 2. This report documents the repair procedures used for the Indian Point Unit 2 steam generators, and includes copies of the Manufacturers Report of Welded Repairs or Alterations for each of the steam generators Nos. 21, 22, 23, and 24. Part 2 of this report supplements Part 1, submitted previously as an enclosure to a Consolidated Edison Company letter, dated March 28, 1972.

Sincerely,

Richard C. DeYoung, Assistant Director
for Pressurized Water Reactors
Directorate of Licensing

Enclosures:
As stated

Distribution:
Docket
PWR-2 R/F
NBrown (2)

8111230191 720613
PDR ADOCK 05000247
PDR

OFFICE ▶	AD:PWR	PWR-2				
SURNAME ▶	SBachrach <i>SB</i>	KKniel <i>KK</i>				<i>Raw</i>
DATE ▶	6/13/72	6/13/72				