


William J. Cahill, Jr.  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N.Y. 10003  
Telephone (212) 460-3819

June 25, 1976  
Re Indian Point Unit No. 3  
Docket No. 50-286  
R.O. -76-3-20(A)

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
Region 1  
U.S. Nuclear Regulatory Commission  
King of Prussia, PA 19406

Regulatory



Dear Mr. O'Reilly:

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64 the attached report of Reportable Occurrence R.O.-76-3-20(A) is submitted. This report fulfills the requirement for a written report within 14 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours,


William J. Cahill, Jr.  
Vice President

Enc:  
nvg

Copy to Director of Nuclear Reactor Regulation  
ATTN: Dr. Ernst Volgenau, Director (40 copies)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director of Nuclear Reactor Regulation  
ATTN: Mr. William G. McDonald, Director (3 copies)  
Office of Management Information and  
Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, N.Y. 10019



6464