

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Kruger Technologies, Inc. (KTI) P. O. Box 201 Knob Noster, MO 65336 REPORT NUMBER(S)	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351
---	---

3. DOCKET NUMBER(S) 030-30164	4. LICENSEE NUMBER(S) 24-25827-01	5. DATE(S) OF INSPECTION December 28, 2009
---	---	--

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG 1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Robert P. Hays		12/28/09

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Kruger Technologies, Inc. (KTI)		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
REPORT NUMBER(S) 2009-01			
3. DOCKET NUMBER(S) 03030164	4. LICENSE NUMBER(S) 24-25827-01	5. DATE(S) OF INSPECTION December 28, 2009	
6. INSPECTION PROCEDURES USED 87124 (11/25/03)		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Calvin Hiebert, RSO	4. TELEPHONE NUMBER 660-563-5886
------------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: **December 2014**

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This inspection was conducted as a follow-up to escalated enforcement. During a routine inspection conducted on June 12, 2009, the inspector identified a violation of 10 CFR 30.34(i), concerning the security of a portable moisture-density gauge at the licensee's authorized storage location.

Licensee personnel demonstrated the proper security of the gauge while in storage at the licensee's authorized storage location. The inspector noted that the licensee stored the gauge as described in their letter dated July 27, 2009, meeting the requirements of 10 CFR 30.34(i). Licensee personnel also described the training that took place following identification of the violation to ensure that gauge operators understood the application of the requirement. Based on this information, the inspector determined that the licensee has corrected the violation identified during the June 2009 inspection, and has implemented the corrective actions described in response to the violation. Based upon the reviewed corrective actions taken, the violation is considered closed.

