


**Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR**



Note: Directions are directions that the plume is headed. Values can be converted to lbm/100-acre-month by multiplying by 0.893.

Figure 2.3-375 CPNPP Cooling Tower Annual Total Dissolved Solids Deposition