

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR




Figure 2.5.4-236 Fully-Softened Direct Shear Test Range with Triaxial Test Data