

APR 13 1972

Samuel W. Jensch, Esq., Chairman  
Atomic Safety and Licensing Board  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Mr. R. B. Briggs, Director  
Molten-Salt Reactor Program  
Oak Ridge National Laboratory  
P. O. Box Y  
Oak Ridge, Tennessee 37830

Dr. John C. Geyer, Chairman  
Department of Geography and  
Environmental Engineering  
The Johns Hopkins University  
Baltimore, Maryland 21218

In the Matter of Consolidated Edison Company of New York, Inc.  
Indian Point Nuclear Generating Unit No. 2  
Docket No. 50-247

Gentlemen:

Pursuant to the request of the Board at the last session of the hearing in subject proceeding held on April 5, 1972 (TR-4766), the following is the corrected response of the regulatory staff to intervenor's finding # 9.

"The definition of loss-of-coolant accidents as given in 10 CFR Part 50 limits the size of reactor coolant pressure boundary break to that equivalent to a double-ended break of the largest pipe of the reactor coolant system."

Sincerely,

Myron Karman  
Counsel for AEC Regulatory Staff

cc: J. Bruce MacDonald, Esq.  
Angus Macbeth, Esq.  
Anthony Z. Roisman, Esq.  
Honorable William J. Burke  
Paul S. Shemin, Esq.

Leonard M. Trosten, Esq.  
Atomic Safety & Licensing Board Panel  
Algie A. Wells, Esq.  
Stanley T. Robinson, Jr.

OFFICE ▶	OGC				
SURNAME ▶	MKarman	8111050156 720413 PDR ADOCK 05000247 G			Leaving
DATE ▶	4/12/72				