

LAW OFFICES OF  
LEBOEUF, LAMB, LEIBY & MACRAE  
1821 JEFFERSON PLACE, N.W.  
WASHINGTON, D. C. 20036


ARVIN E. UPTON  
EUGENE B. THOMAS, JR.  
LEONARD M. TROSTEN  
HARRY H. VOIGT  
ALEX K. LARSON  
WASHINGTON PARTNERS

June 28, 1973

ONE CHASE MANHATTAN PLAZA  
NEW YORK, N. Y. 10005

WASHINGTON TELEPHONE  
202 FEDERAL 8-0111

CABLE ADDRESS  
LALALU, WASHINGTON D. C.



Samuel W. Jensch, Esq.  
Chairman  
Atomic Safety & Licensing Board  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Re: Consolidated Edison Company  
of New York, Inc.  
Indian Point Unit No. 2  
AEC Docket No. 50-247

Dear Mr. Chairman:

Having completed the maintenance and adjustments described in our letter of June 14, 1973 and the document entitled, "50-Day Report of the Indian Point Unit No. 2 Testing Program" and required hydrostatic testing, the reactor was again taken critical on June 26, 1973. On June 26, 1973, at 1:40 p.m., the main generator of Indian Point 2 was synchronized to the Consolidated Edison system for the first time. The power level was increased over a period of several hours to approximately 90 MW<sub>e</sub> (gross). At that time a generator trip occurred due to spurious actuation of transformer protective instrumentation. The reactor was brought to the hot shutdown condition while minor maintenance and adjustments were performed on this instrumentation. On June 27, 1973 the plant was again brought to a power level of approximately 90 MW<sub>e</sub> and held at that level for several hours in preparation for a

8110240425 730628  
PDR ADOCK 05000247  
S PDR

planned unit trip to test the turbine overspeed protection device.

Very truly yours,

LEBOEUF, LAMB, LEIBY & MACRAE  
Attorneys for Applicant

By Edward L. Cohen  
Edward L. Cohen

- cc: Mr. R. B. Briggs
- Dr. John C. Geyer
- Myron Karman, Esq.
- Anthony Z. Roisman, Esq.
- Angus Macbeth, Esq.
- J. Bruce MacDonald, Esq.
- Honorable Louis J. Lefkowitz
- Secretary, USAEC (2)
- Atomic Safety and Licensing Board Panel