

John D. O'Toole
Assistant Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-2533

December 1, 1980

Re: Indian Point Unit No. 2
Docket No. 50-247

RECEIVED DISTRIBUTION
SERVICES UNIT

1980 DEC 9 PM 12 44

US HRC
DISTRIBUTION SERVICES
BRANCH

Director of Nuclear Reactor Regulation
ATTN: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Eisenhut:

The preliminary clarifications forwarded by your September 5, 1980 letter requested documentation of the actions taken to satisfy item II.K.3.9 of the TMI Action Plan. Regarding the proportional integral derivative (PID) controller function associated with the PORV 455C at Indian Point Unit No. 2, the derivative action has been removed from the controller. There is no derivative function associated with PORV 456.

Should you or your staff have any further questions, please contact us.

Very truly yours,

John D. O'Toole

*Asst
S/P*

8012100 489

P