



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3942

September 5, 1969

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Branch
Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2 (IP-2)
DOCKET NO. 50-247

The attached report of a visit to the subject facility on
July 23 and 24, 1969, is forwarded for information.

In response to previously reported pipe deficiency allegations, an extensive program by Con Ed is continuing in an effort to establish code compliance for all stainless steel piping and fittings. The Con Ed program has included visits to Dravo, the supplier of all stainless pipe, as well as visits to vendors supplying material to Dravo. The most significant deficiencies detected at this point are instances of unauthorized material substitutions, deviations from chemical limits in purchase specifications and lack of evidence to support nondestructive testing. Each of the deficiencies is receiving further attention by Con Ed in an attempt to obtain satisfactory resolution.

N. C. Moseley
Senior Reactor Inspector

Attachment:

CO Report No. 247/69-8
by G. L. Madsen, dtd 8/27/69

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
Regional Directors, CO
✓ REG Files

8111030041 690905
PDR ADOCK 05000247
PDR
Q

RECEIVED

1969 SEP 8 AM 11 01

U.S. ATOMIC ENERGY COMM.
DIVISION OF COMPLIANCE