



UNITED STATES
ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE

REGION I

970 BROAD STREET

NEWARK, NEW JERSEY 07102

201 645-

JUL 11 1969

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Br.,
Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY - INDIAN POINT NO. 2
DOCKET NO. 50-247

The attached report of visits to the subject facility on April 17,
May 15, 22 and 23, 1969, is forwarded for information. No items of
nonconformance and no safety items were identified.

Resolution has been made of a number of the apparent discrepancies
detected in the short initial review of the general piping allegations.
The licensee has a continuing program which is responsive to our
initial concerns. It is still too early to evaluate whether the
program will be as extensive as we may desire. We will continue to
follow this matter.

A number of repairs are required on primary system field welds. We
will followup on the satisfactory completion of this work.

This report discusses the resolution to a number of problems which
have been outstanding from the last several inspections.

for M. J. Hildreth
N. C. Moseley,
Senior Reactor Inspector

Attachment:

CO Report No. 247/69-6
by G. L. Madsen, dtd 6/26/69

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
Regional Directors, CO
REG File

DIVISION OF COMPLIANCE
NEWARK, NEW JERSEY 07102

RECEIVED

8111030081 690711
PDR ADOCK 05000247
Q PDR

RECEIVED

1969 JUL 14 PM 1 53

U.S. ATOMIC ENERGY COMM.
DIVISION OF COMPLIANCE

TO: DIRECTOR, DIVISION OF COMPLIANCE

FROM: SAC, [illegible]

RE: [illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]