



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645-

DEC 24 1968

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Br.,  
Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY - INDIAN POINT NO. 2  
DOCKET NO. 50-247

The attached report of a visit to the subject facility on November 20 and 21, 1968, is forwarded for information.

An item of safety concern is that additional deficiencies were discovered by the licensee in carbon steel piping furnished by Dravo Company. The licensee is continuing to investigate this problem. Compliance has scheduled a vendor inspection of the Dravo Company on January 7 - 9, 1969. Region I plans to make a detailed review of the Con Ed investigation during the next inspection visit.

During this inspection visit our inspector noted considerable improvement in the storage and protection of equipment.

*N. C. Moseley*  
N. C. Moseley  
Senior Reactor Inspector

Attachment:

CO Report No. 247/68-6  
by G. L. Madsen, dtd 12/17/68

cc: E. G. Case, DRS  
R. S. Boyd, DRL (2)  
S. Levine, DRL (6)  
D. J. Skovholt, DRL (3)  
L. Kornblith, Jr., CO  
Regional Directors, CO  
→ REG files

8111030205 681224  
PDR ADDCK 05000247  
Q PDR