


UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3942



May 26, 1971

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch,
Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY (INDIAN POINT NO. 2)
DOCKET NO. 50-247

The attached report of inspections at the subject facility on April 6, 7, 8, 21 and 22, 1971 is forwarded for information.

The polar crane leg failure appears to have been adequately resolved by Con Ed.

The previously identified concern about electrical and instrument jumpers has been resolved in our review. Adequate controls appear to be provided for future testing.

Only one construction logbook item is still outstanding. We believe that adequate resolution will be provided for this item.

N. C. Moseley
Senior Reactor Inspector

Enclosure:

CO Report No. 247/71-8
by G. L. Madsen dtd 5/13/71

cc: E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
P. W. Howe, DRL (2)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
Regional Directors, CO
REG Files
J. B. Henderson, CO

8111110668 710526
PDR ADOCK 05000247
G PDR