



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3942

October 28, 1970

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch,
Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY (INDIAN POINT NO. 2)
DOCKET NO. 50-247

The attached report of inspections at the subject facility on September 8, 23 and 25, 1970 is forwarded for information. No previously unidentified areas of concern were detected.

The pressurizer question was reviewed in a meeting on October 7, 1970 with Con Ed, Westinghouse and Con Ed consultants. Several questions remain outstanding and Con Ed has been requested to furnish a report to DRL covering the entire subject. The significant results of the October 7, 1970 meeting will be covered in the next inspection report.

N. C. Moseley
Senior Reactor Inspector

Enclosure:

CO Report No. 247/70-9
by G. L. Madsen dtd 10/21/70

cc: E. G. Case, DRS (3)
~~P. A. Morris, DRL~~
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
P. W. Howe, DRL (2)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
Regional Directors, CO
REG Files

811111114 701028
PDR ADCK 0500247
Q PDR