

UNITED STATES ATOMIC ENERGY COMMISSION DIVISION OF COMPLIANCE REGION I 970 BROAD STREET NEWARK, NEW JERSEY 07102

April 6, 1972

.....

201 645. 3942

J. G. Keppler, Chief, Reactor Testing & Operations Branch, Division of Compliance, HQ

CO INQUIRY REPORT NO. 50-247/72-11 CONSOLIDATED EDISON COMPANY INDIAN POINT 2 - PWR OPERATOR ERROR - PRIMARY SYSTEM PRESSURE SURGE

The subject inquiry report is forwarded for your information.

Similar pressure surges were encountered on February 16 and 17 and March 8, 1972 and reports were submitted to DRL.

A copy of the TWX from the licensee is enclosed.

Eldon J. Brunner

Senior Reactor Inspector

Enclosure: Subject Inquiry Report

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
L. Kornblith, CO
R. H. Engelken, CO
J. B. Henderson, CO
CO Files
DP Control Files



