



UNITED STATES
ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 6453942

August 19, 1971



J. G. Keppler, Chief, Reactor Testing & Operations Branch
Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY (INDIAN POINT NO. 2)
DOCKET NO. 050-247

The attached report of a meeting with New York State organizations to review emergency planning for Indian Point No. 2 is forwarded for information.

The inspection results indicate that the New York State Health Department and State Police are adequately prepared for emergency situations. The inspectors believe that a shortcoming in the present state of readiness is that no tests have been made of implementation of the plan. Furthermore, we understand that the only tests planned are for the communications systems.

Review of the Hospital Emergency planning as required by PI 2000/3 will be covered in a subsequent report.

N. C. Moseley
Senior Reactor Inspector

Enclosure:
Inspection Report
No. 50-247/71-11
dated 8/19/71
by G. L. Madsen

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
Regional Directors, CO
DR Central Files
J. B. Henderson, CO

811120633 710819
PDR ADDCK 05000247
Q PDR