


R.E.G files

UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645. 3942



July 2, 1971

J. P. O'Reilly, Chief, Reactor Testing and Operations Branch,  
Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY (INDIAN POINT 2)  
DOCKET NO. 50-247

The attached report of an inspection at the subject site on May 4, 5, 14, 26 and 27, 1971 is forwarded for information. No items of non-conformance and no safety items were observed or reported.

Progress is being made in resolving our previous concerns for preoperational testing, power ascension and operating procedures. If the present course is followed by Con Ed, we believe that satisfactory resolution will be made.

A major limiting item for construction completion continues to be installation of pipe hangers and restraints. We expect Con Ed to ask for a core loading license when the hearing resumes on July 13, 1971. It is believed that they may be able to meet the DRL requirements for the "early core loading" at that time.

At this time the fencing and access control is not yet in accordance with the FSAR description. An item we have questioned is that no fence is planned (even in the FSAR) for the river front area.

We are expediting completion of our review of the emergency plan procedures and related arrangements with state and local agencies. This review is expected to be completed prior to the hearing resumption.

*G. L. Madsen* for  
N. C. Moseley  
Senior Reactor Inspector

Enclosure:  
CO Report No. 247/71-9  
by G. L. Madsen dtd 6/23/71

8111120643 710702  
PDR ADOCK 05000247  
PDR  
Q

J. P. O'Reilly

- 2 -

cc: E. G. Case, DRS (3)  
P. A. Morris, DRL  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
P. W. Howe, DRL (2)  
A. Giambusso, CO  
L. Kornblith, Jr., CO  
R. H. Engelken, CO  
Regional Directors, CO  
REG Files ✓  
J. B. Henderson, CO