

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

April 27, 1976

Docket Nos. 50-247
50-286

Re: I.E. Insp. Nos. 50-247/76-03
50-286/76-05

Mr. Paul R. Nelson, Chief
Fuel Facility and Material Safety Branch
U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406


Dear Mr. Nelson

This letter constitutes our reply to your letter of April 2, 1976 relative to your inspection of our Indian Point Nuclear Power Station conducted on February 23-25, 1976. As noted, each of the reported deficiencies has already been satisfactorily resolved. Therefore, this reply is being limited to those steps taken by us to prevent similar items of noncompliance. These steps are noted below:

1. We are conducting a detailed review of the requirements for procedures as specified in Appendix B to our Technical Specifications. This review should be completed by June 30, 1976. Any procedural deficiencies noted during the course of this review will be corrected as soon as possible.
2. Future technical specification changes will be reviewed carefully before such changes are submitted for approval to determine any requirement for new procedures or procedure review.

The above steps should insure that we will remain in full compliance with all procedure requirements.

Very truly yours


William J. Cahill, Jr.
Vice President

8111240815 760511
PDR ADOCK 05000247
PDR
Q