

**Murray Selman**  
Vice President

Consolidated Edison Company of New York, Inc.  
Indian Point Station  
Broadway & Bleakley Avenue  
Buchanan, NY 10511  
Telephone (914) 737-8116

May 5, 1987

Mr. Robert M. Gallo, Chief  
Projects Branch No. 2  
Division of Reactor Projects  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Re: Consolidated Edison Company of New York, Inc.  
Indian Point Station Unit No. 2  
Docket No. 50-247

Subject: Routine Inspection 50-247/86-29

Dear Mr. Gallo:

This is in response to your letter of March 20, 1987 concerning the requalification program evaluation report prepared by Mr. N. Dudley as a result of the evaluation conducted at Indian Point Unit 2 during December 10-12, 1986.

The summary of the report requested that Con Edison further describe what additional training and evaluation will be conducted prior to allowing a staff engineer to resume the functions of an operator or a senior operator. In our letter of February 4, 1987 to Mr. W. F. Kane regarding routine inspection No. 50-247/86-28 we described corrective action to enforce the provisions of 10CFR55.31(e) dealing with performance of operators. Subsequent to that letter, the NRC issued an extensive rule change to 10 CFR Parts 50 and 55 dealing with operators' licenses. The issue of active status of operator or senior reactor operators is addressed in the rule. Staff engineer licenses are thereby covered by the rule.

Since our earlier reply to the NRC stated that a station policy covering licensed operator training and requalification had been written, we will revise that policy and incorporate the conditions and requirements of the 10 CFR 55 final rule. This will ensure that any staff engineer has the necessary proficiency before assuming an active position which utilizes the person's license. Our policy will be revised and implemented prior to May 26, 1987.

Should you or your staff have any questions, please contact us.

Very truly yours,

*Murray Selman*

8705130145 870505  
PDR ADOCK 05000247  
G PDR

IE01  
110

20.190.4.13.6

cc: Regional Administrator - Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Senior Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 38  
Buchanan, NY 10511