Docket Nos. 50-247

Consolidated Edison Company of
New York, Inc.
ATTN: Mr. Murray Selman
Vice President, Nuclear Power
Indian Point Station
Broadway and Bleakley Avenue
Buchanan, New York 10511

Gentlemen:

Subject: Inspection No. 50-247/87-35

This letter refers to the routine inspection conducted by Mr. Harry W. Kerch of this office on December 7-9, 1987, at Indian Point Nuclear Generating Station, Unit 2, Buchanan, New York. Mr. Harry W. Kerch discussed the findings of the inspection with you and members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

William V. Johnston, Acting Director

Division of Reactor Safety

Enclosure: NRC Region I Inspection Report No. 50-247/87-35

8802170128 880208 PDR ADDCK 05000247

102

OFFICIAL RECORD COPY

IR IP2 87-35 - 0001.0.0 01/26/88

cc w/encl:
Jude G. Del Percio, Manager, Regulatory Affairs
P. Kokolakis, Director, Nuclear Licensing
Brent L. Brandenburg, Assistant General Counsel
Walter Stein, Secretary - NFSC
Public Document Room (PDR)

Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)

NRC Resident Inspector State of New York

bcc w/encl:

Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
DRP Section Chief
Robert J. Bores, DRSS
C. Y. Cheng, NRR

RI:DRS Kerch/sh/rw

RI:DRS Strosnider

RID: DRS

1/11 /88

1/ 11/88

1/12/88