

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N.Y. 10003  
Telephone (212) 460-3819

November 26, 1976  
Re: Indian Point Unit No. 3  
Docket No. 50-286

Mr. James P. O'Reilly, Director  
Office on Inspection and Enforcement  
Region 1  
U.S. Nuclear Regulatory Commission  
631 Park Ave  
King of Prussia, Pa 19406


Dear Mr. O'Reilly:

In accordance with the requirements of Paragraph 6.9.1 of the Technical Specifications to Facility Operating License DPR-64, forwarded herewith are two copies of a report entitled, "Startup Test Report - Indian Point Unit No. 3 Reactor".

The special report required by Paragraph 6.9.2a of the Technical Specifications is included in this report as Section 5.10.3.

Supplemental reports on the uncompleted tests (Hundred Hour Acceptance Test, Steam Generator Moisture Carryover and 50% Load Rejection from 100% Power) will be forwarded to you after their completion.

Very truly yours,

  
William J. Cahill, Jr.  
Vice President

Enc: *see Rpts*  
RR/mc

Copy to: Director of Nuclear Reactor Regulation  
ATTN: Dr. Ernst Volgenau, Director (25 copies)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director of Nuclear Reactor Regulation  
ATTN: Mr. William G. McDonald, Director (2 copies)  
Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, N.Y. 10019