

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-5042

September 24, 1973

Mr. E. M. Howard, Chief
Facility Construction & Engineering Support Branch
Directorate of Regulatory Operations
Region 1
U.S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Howard

In reply to your letter of August 20, 1973, concerning the inspection conducted by Mr. Allentuck on July 16, 17, and 18, 1973 at our Indian Point Unit No. 3 facility, we have the following response to the item listed in the enclosure to your letter:

Response: Item 1

The following corrective action has been taken:

1. The stick file in question has been updated with the latest revisions.
2. Quality Control inspectors have been re-instructed to use drawings from the Quality Control files only. Proper control of these files has been verified by audits conducted by both Con Edison and WEDCO. Periodic audits of the Wedco Quality Control files and the Construction Engineering files will be performed.
3. The electrical subcontractor involved has been instructed to do the following:
 - a. Place drawing revisions on the field stick files immediately upon receipt.
 - b. Stamp "Reference Only" any previous issue kept on the field stick files, and

811140620 731015
PDR ADOCK 05000286
G PDR

September 24, 1973

- c. Perform periodic audits of his office and field stick files to ensure that only current revisions are in use.

It is expected that full compliance with the above corrective action will be accomplished by September 30, 1973.

Very truly yours

A handwritten signature in cursive script, appearing to read "Peter J. Conradi". The signature is written in dark ink and is positioned below the typed text "Very truly yours".