

Carl L. Newman
Vice President

Regulatory



File Cy

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133

September 19, 1975

Re Indian Point Unit No. 3
Docket No. 50-286

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406



Dear Mr. O'Reilly

On April 5, 1975 pursuant to 10CFR50.55(e) of the Commission's Regulations your office was notified by telephone of apparent dye penetrant indications in the cladding of No. 31 steam generator. Subsequent examinations revealed indications in the other steam generators. On May 5, 1975 an interim report was forwarded to you.

Our investigation of this matter is now completed. Our final report, "Technical Report on Steam Generator Channel Head Cladding Indian Point Unit No. 3" describing this program is enclosed for your consideration. Appendix D of this report which will describe the proposed in-service inspection method will be provided as soon as possible.

Very truly yours

John D. Frole
for Carl L. Newman
Vice President

Enc.
mrb

Copy to Mr. A. Giambusso, Director (20 Copies)
Division of Reactor Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

10078

8111180562 750919
PDR ADOCK 05000286
S PDR