

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

January 6, 1975

Re License No. CPPR-62  
Inspection No. 50-286/74-22

Mr. Robert T. Carlson, Chief  
Facility Construction and Engineering  
Support Branch  
U.S. Atomic Energy Commission  
Directorate of Regulatory Operations  
Region 1  
631 Park Avenue  
King of Prussia, Pa. 19406


Dear Mr. Carlson:

This is in response to your letter of November 27, 1974 notifying us of a violation found during an inspection conducted by Mr. Folsom of your office on November 11-13, 1974.

All non-installed hydraulic seismic restraints for Indian Point Unit No. 3 have now been properly stored and protected in designated areas. Proper storage and protection was confirmed and documented during a recent WEDCO Quality Assurance audit. Regarding the particular restraints in question (i.e., restraints RC-R-343-4AH and RC-R-343-4BH), such restraints were installed on November 18, 1974 after being inspected and accepted by the WEDCO Quality Control group.

Regarding the identity of the attachments for the hydraulic seismic restraints, such attachments are considered stock items. Unique identification is not a requirement. Also, due to physical geometry of the various size restraints and attachments, they cannot be improperly interchanged.

Very truly yours,



William J. Cahill, Jr.  
Vice President

8111180595 750116  
PDR ADOCK 05000286  
G PDR

DEC 18 1974

Dockets Nos. 50-3  
50-247  
and 50-286 ✓

Consolidated Edison Company  
of New York, Inc.  
ATTN: Mr. William J. Cahill, Jr.  
Vice President  
4 Irving Place  
New York, New York 10003

DISTRIBUTION:  
AEC PDR  
Local PDR  
Dockets (3)  
ORB#3 Rdg  
KRGoller  
TJCarter  
GLear  
PBERickson  
SATEets  
RO (3)  
OGC  
extra cps  
HDenton  
CSteppe  
LShao  
Gluckman

Gentlemen:

A copy of our report "Geologic and Seismic Evaluation of the  
Indian Point Site" is enclosed for your information.

Sincerely,

Original Signed

George Lear, Chief  
Operating Reactors Branch #3  
Directorate of Licensing

Enclosure:  
As Stated

cc: Leonard M. Trosten, Esquire  
LeRoeuf, Lamb, Leiby & MacRae  
1757 N Street, N. W.  
Washington, D. C. 20036

Honorable George Segnit  
Mayor, Village of Buchanan  
188 Westchester Avenue  
Buchanan, New York 10511

Dr. William E. Seymour  
Staff Coordinator  
New York State Department of Commerce  
New York State Atomic Energy Council  
99 Washington Street  
Albany, New York 12210

Mrs. Kay Winter, Librarian  
Hendrick Hudson Free Library  
31 Albany Post Road

OFFICE ➤	Montrose, New York 10548	ORB#3	ORB#3	<i>Mr. E</i>
SURNAME ➤		Erickson:kmf	GLear	
DATE ➤		12/ /74	12/ /74	