

William J. Cahill, Jr.
Vice President


Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

June 3, 1976

Re Indian Point Unit No. 3
Docket No. 50-286
R.O.-76-3-9(B)
-76-3-10(B)

Regulatory Docket File

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
King of Prussia, Penn. 19406



Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64, the attached reports of Reportable Occurrences R.O. 76-3-9(B) and R.O. 76-3-10(B) are submitted. These reports fulfill the requirement for written reports within thirty days of Reportable Occurrences and are in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.


Three copies of this letter and the attachments are attached as required.

Very truly yours

William J. Cahill, Jr.
Vice President

attach.
mk

Copy to Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (30 copies)
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, N. Y. 10019

5830

8111070574 760603
PDR ADCK 05000286
S PDR