

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



September 29, 1978
IP-FWG-2978

Re: Docket No. 50-286

Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

REGULATORY DOCKET FILE COPY

Dear Mr. Grier:

The attached Licensee Event Report LER 78-027/03L-0 is hereby submitted for your information. It should be noted, however, that one level transmitter was operable as per Technical Specification 3.3.A.1.d. Had this transmitter not been available, the event would be reportable in accordance with requirements of 6.9.1(b).

Very truly yours

J. P. Bayne
Resident Manager

1978
OCT 4
AM 11 42
DISTRIBUTION SERVICES

RECEIVED DISTRIBUTION SERVICES UNIT

FWG/rbb
Attachment

cc: Director of Nuclear Reactor Regulation
Attn: William McDonald, Director (3 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Office of Inspection and Enforcement (30 copies)
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

Resident Inspector T. Rebelowski
George Wilverding, NYO
P. W. Lyon, NYO
James Davis (SRC), NYO

REGULATORY DOCKET FILE COPY

780660238

A002/s*
1/3

8111090181 780929
PDR ADOCK 05000286
S PDR