

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



50-286
September 1, 1978
IP-NAP-2509

RECEIVED
DISTRIBUTION
SERVICES UNIT

1978 SEP 11 9 51

Mr. Boyce Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Update Report LER 78-017/03L-1 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.8.(a). The event occurred as a result of a periodically tested equipment setting deviating from required tolerance.

Very truly yours,

J. D. Bayne
J. D. Bayne
Resident Manager

NAP:ms

cc: Director of Nuclear Reactor Regulation
Attn: Mr. William McDonald, Director (3 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Office of Inspection and Enforcement (30 copies)
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

8111090315 780901
PDR ADDCK 05000286
S PDR

782480126

A002
5/1