

POWER AUTHORITY OF THE STATE OF NEW YORK  
INDIAN POINT NO. 3 NUCLEAR POWER PLANT  
P. O. BOX 215 BUCHANAN, N. Y. 10511  
TELEPHONE: 914-739-8200



50-280

September 1, 1978  
IP-NAP-2509

1978 SEP 11 9 51

RECEIVED DISTRIBUTION SERVICES UNIT

DISTRIBUTION SERVICES

Mr. Boyce Grier, Director  
Office of Inspection and Enforcement  
Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Update Report LER 78-017/03L-1 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.8.(a). The event occurred as a result of a periodically tested equipment setting deviating from required tolerance.

Very truly yours,

*J. D. Bayne*  
J. D. Bayne  
Resident Manager

NAP;ms

cc: Director of Nuclear Reactor Regulation  
Attn: Mr. William McDonald, Director (3 copies)  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Office of Inspection and Enforcement (30 copies)  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

8111090315 780901  
PDR ADDCK 05000286  
S PDR

782480126

A002  
5/11