

POWER AUTHORITY OF THE STATE OF NEW YORK

INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



REGULATORY DOCKET FILE COPY

August 24, 1978


IP-NAP-2466

Mr. Boyce Grier, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Update Report LER 78-010/3L-1 is hereby submitted for your information. It should be noted, however, that sufficient valves were available as per Technical Specification 3.4.C. Had an insufficient number of valves been available, the event would be reportable in accordance with requirements of 6.9.1.8.(b).

Very truly yours,


J. P. Bayne
Resident Manager

NAP/bal

cc: Director of Nuclear Reactor Regulation
Attn: Mr. William McDonald, Director (3 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dr. Ernst Volgenau (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. George T. Berry
General Manager and Chief Engineer
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

8111090384 780824
PDR ADCK 05000286
S PDR

782370299

A002
S, //

1978 AUG 24 PM 12 CC
DISTRIBUTION SERVICES UNIT
U.S. NUCLEAR REGULATORY COMMISSION
DISTRIBUTION SERVICES