

POWER AUTHORITY OF THE STATE OF NEW YORK  
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200

50-286

REGULATORY DOCKET FILE COPY



August 1, 1978  
IP-NAP-2226

Mr. Boyce Grier, Director  
Office of Inspection and Enforcement  
Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

REGISTRATION  
SERVICES UNIT  
1978 AUG 2 11 27  
REGISTRATION  
SERVICES UNIT

Dear Mr. Grier:

The attached Licensee Event Report LER 78-014/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.8.(a). The event occurred as a result of a periodically tested equipment operating in a degraded mode.

Very truly yours,

*J. P. Bayne*  
for J. P. Bayne  
Resident Manager

NAP/rbb

cc: Director of Nuclear Reactor Regulation  
Attn: Mr. William McDonald, Director (2 copies)  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dr. Ernst Volgenau (40 copies)  
Office of Inspection and Enforcement  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

782160028

8111090724 780801  
PDR ADOCK 05000286  
S PDR

4002  
5/11