

POWER AUTHORITY OF **REGULATORY BOOKET FILE COPY**
10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019
(212) 397-6200

TRUSTEES
FREDERICK R. CLARK
CHAIRMAN
GEORGE L. INGALLS
VICE CHAIRMAN
RICHARD M. FLYNN
ROBERT I. MILLONZI
WILLIAM F. LUDDY



June 9, 1978
IPO-116

GEORGE T. BERRY
GENERAL MANAGER
AND CHIEF ENGINEER
LEWIS R. BENNETT
ASSISTANT GENERAL
MANAGER-GENERAL
COUNSEL
WILBUR L. GRONBERG
ASSISTANT GENERAL
MANAGER-ENGINEERING
JOHN W. BOSTON
DIRECTOR OF
POWER OPERATIONS
THOMAS F. MCCRANN, JR.
CONTROLLER

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief
Operating Reactors Branch No. 1

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286




Dear Mr. Schwencer:

By letter dated February 27, 1978 Consolidated Edison Company of New York, Inc. requested an extension for the submittal of information requested by your letters of September 14 and October 27, 1977 relative to lamellar tearing of Steam Generator and Reactor Coolant Pump supports.

At that time, it was anticipated that responses to your questions could be provided by June 1, 1978; however, our NSSS vendor will now provide us with a compilation of plant data in September, 1978. It is now expected that responses can be submitted by September 29, 1978.

Very truly yours,


P. J. Early
Assistant Chief Engineer-
Projects

781650019

8111120351 780609
PDR ADOCK 05000286
PDR

A018/s *
110

NUCLEAR REGULATORY COMMISSION
DAILY ACCESSION LIST

05/10/78

PAGE 29

FILE LOCATION

13
124-0046
ATTER
*IP

TASK NBR:
FICHE NBR :
NOTARIZED: NO
LPDR: YES CLASS:

RECP AFFILIATION: NRC
ORG AFFILIATION: CONSOL EDISON OF NY

REGULATORY LICENSEE EVENT REPT (RO 50-286/78-006/032L) ON 03/28/78 CONCERNING A
EILINGERSOLL-RAND, MODEL NO 3X20W, NO 036751 GASKET BETWEEN MECHANICAL
AND PLATE AND PUMP CASING WAS FOUND TO BE LEAKING AND WAS REPLACED.

124-0047
ATTER
*IP

TASK NBR:
FICHE NBR :
NOTARIZED: NO
LPDR: NO CLASS:

RECP AFFILIATION: NRC
ORG AFFILIATION: CONSOL EDISON OF NY

REGULATORY LICENSEE EVENT REPT (RO 50-286/78-007/03L) ON 03/31/78 CONCERNING
NORMAL OPERATION, PROCESS RADIATION MONITOR R-11 AND ASSOCIATED MONITOR
TIME INOPERABLE DUE TO A TRIPPED SAMPLE PUMP.

146-0255
10

TASK NBR:
FICHE NBR :
NOTARIZED: NO
LPDR: NO CLASS:

RECP AFFILIATION: NRC
ORG AFFILIATION: NRC

TITLED "EARTHQUAKES, FAULTS, AND NUC PLANTS IN SOUTHERN NEW YORK &
NEW JERSEY", FOR TRANSMITTAL TO THE BD.