POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019
(212) 397-6200



July 10, 1979 IPN-79-46

Director, Office of Nuclear Reactor Regulation U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief

Operating Reactors Branch No. 1 Division of Operating Reactors

Subject:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286

I&E Bulletin 79-07 Status Report

on Pipe Stress Reanalysis

Dear Sir:

Attached for your information is the weekly status report as of July 6, 1979 on United Engineers & Constructors piping reanalysis efforts for the critical lines committed under our letter of May 31, 1979.

Very truly yours,

Paul/J. Early

Assistant Chief Engineer-Projects

100/1

Indian Point 3 Nuclear Power Plant Pipe Stress Reanalysis Status of Work as of July 6, 1979

A. Piping

Total No. of Lines for Reanalysis	•		No. of Lines Within Allowables	No. of Lines Over Allowables
176		89	89	0
			_	

B. Piping Supports, Hangers, Snubbers & Nozzles

Total No. of Components to Reanalyze Total No. Reanalyzed		No. of Components Within Original Design Loads and/ or Allowables	No. of Components Over Design Loads and/or Allowables
1462 (1)	451	451	0

Notes:

(1) Estimated quantities