

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



May 31, 1979

IP-MEA-5003

Docket No. 50-286


License No. DPR-64

Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

With regard to I. E. Bulletin No. 79-11, it has been determined that none of the Westinghouse type DB50 or DB75 breakers with overcurrent protection are utilized in safety-related systems at Indian Point 3 Nuclear Power Plant. We, therefore, conclude that the provisions of I.E. Bulletin No. 79-11 are not applicable to our facility and no further action is required.

Very truly yours,



J. P. Bayne
Resident Manager

MEA/rbb

REC-2
200

7907050249