

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200



August 27, 1979

IPN-79-65

REGULATORY DOCKET FILE COPY

Director, Office of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief
Operating Reactors Branch No. 1
Division of Operating Reactors

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
I&E Bulletin 79-07 Status Report
on Pipe Stress Reanalysis

Dear Sir:

Attached for your information is the weekly status report as of August 25, 1979 on United Engineers and Constructors piping reanalysis efforts for the critical lines committed under our letter of May 31, 1979.

Very truly yours,

A handwritten signature in dark ink, appearing to read 'Paul J. Early', is written over the typed name.

Paul J. Early
Assistant Chief Engineer-Projects

A001
5/11

7909040 516

Indian Point 3 Nuclear Power Plant
 Pipe Stress Reanalysis
 Status of Work as of August 25, 1979

A. Piping

| Total No. of Lines for Reanalysis | Total No. Reanalyzed | No. of Lines Within Allowables | No. of Lines Over Allowables |
|-----------------------------------|----------------------|--------------------------------|------------------------------|
| 176 | 176 | 176 | 0 |

B. Piping Supports, Hangers, Snubbers & Nozzles

| Total No. of Components to Reanalyze | Total No. Reanalyzed | No. of Components Within Original Design Loads and/or Allowables | No. of Components Over Design Loads and/or Allowables |
|--------------------------------------|----------------------|------------------------------------------------------------------|-------------------------------------------------------|
| 1462 ⁽¹⁾ | 1118 | 1118 | 0 |

Notes: (1) Estimated quantities.