

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



December 19, 1979
IP-WDH-6777

Docket No. 50-286
License No. DPR-64

Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: I. E. Bulletin 79-25

Reference: J. P. Bayne to
B. H. Grier
Dated December 17, 1979
IP-MEA-6749

Dear Mr. Grier:

Our December 17, 1979 response to I. E. Bulletin 79-25 contained a typographical error as follows:

The last paragraph of item no. 3 in which overtravel criteria is discussed should read,"the minimum requirement of 0.020 inches,".... vice 0.040 inches as reported.

Very truly yours,

J. P. Bayne
Resident Manager

WDH/bam

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operation Inspection
Washington, D. C. 20555

8001240337

w
HO2