DOCKET NO DAT COMPLETED B TELEPHON eved 100% 11 f 8-18-78	Cense as
eved 100% 11 f 8-18-78 port, Give Reasor	cense as
eved 100% 11 f 8-18-78	cense as
port, Give Reasor	ns:
-	
	·
·	· ·
5831	17568
3937 30	12,918,92
<u></u>	<u> </u>
3702.54	12,543,27
0	0
9,294.365	32,568.925
3,129.471	10,833.111
3,002.303	10,393,682
63.5	71.4
63.5	
	<u> </u>
	61.3_
53.4	4.6
<u> </u>	
<u>    5.5                               </u>	
<u>    53.4                                </u>	

いたらの

INITIAL CRITICALITY INITIAL ELECTRICITY COMMERCIAL OPERATION

AL CRITICALITY	and the second sec	
L ELECTRICITY	N/A	
ERCIAL OPERATION		
7809256059	• [4, φ <sub>1</sub> ], (φ <sub>1</sub> ), (φ <sub>2</sub> ), (φ <sub>1</sub> ), (φ <sub>1</sub> ), (φ <sub>1</sub> ), (φ <sub>1</sub> ), (φ <sub>2</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> )), (φ <sub>1</sub> ), (φ <sub>1</sub> ), (φ <sub>1</sub> ), (φ <sub>1</sub> ), (φ <sub>1</sub>	)/ <sup>*</sup>

. (9/77)

### AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO.	50-286
UNIT	<u>No.3</u>
DATE	September 5, 1978
COMPLETED BY	M. Tagliamonte
TELEPHONE	914-739-8200

TH August 1978		
AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVI (MWe-Net)
	17	
	18	
	19	
	20	
·	21	
	22	
	23	
	24	
	25	
	26	14
	27	313
	28	800
· · · · · · · · · · · · · · · · · · ·	29	834
	30	833
	31	667

16

## INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

Refueling Information Request

- 1. Indian Point No. 3 Nuclear Power Plant
- 2. June 8, 1978
- 3. August 25, 1978
- 4. None
- 5. None
- 6. None
- 7. a)193 b) 64
- 8. 837 assemblies approved capacity
- 9. June 1986 (Full Core Reserve) June 1989 (Without Full Core Reserve)

All scheduled refueling tasks were completed in a timely fashion allowing the unit to return to service on August 25 at 2240. Among the items completed this month were the Integrated Leak Rate Test and assembly of the Turbine after completion of re-wedging of the generator. Initial criticality occurred at 0507 on August 18. After low power physics testing, the turbine was synchronized to the bus at 2240 on August 25. Authorization to operate at 100% rated power was received on August 18, this allows us a 1000 gross mwe output.

#### MONTHLY I & C CATEGORY I REPORT

照日本

-

and the second second of the second sec

A SAME IN A REAL STREET, AND A SAME AND A

. د. '

1.0

:

- C - 2

تمر

				August 1978 Month
Date	W.R. #	Equipment	Malfunction	Corrective Action
8-10-78	I&C-I-00110	IPPI Position El3	Step indicator does not follow increasing or decreasing vol- tage	Found PC board connector loose tightened connector, channel calibrated satisfactorily.
8-16-78	I&C-I-00114	#33 Static inverter	Output voltage reading low	Checked bus voltage, found to be ; correct
8-17-78	1&C-I-00113	LT-934D, accumulator #34 level transmitter	Indicator drifted low	Bypass valve leaked, tightened valve, blowdown impulse lines, returned to proper operation.
		:		
י י ג -		· · ·		

1

A the second second

the and the fight

# MONTHLY MAINTENANCE REPORT

3

August 1978

· "{

DATE -	W.R. #	EQUIPMENT	MALFUNCTION	CORRECTIVE ACTION
t.				
8-3-78	0161-3C	Undervoltage Relays & Alarms	2A, 3A, 5A, 6A buses	Installed undervoltage relays and alarms
-29-78	0216-02	FCV 405B #32 ABFP Discharge Valve to #32 S/G	Will not operate	Replaced cable, bonnet gasket, packin set stroke
-2-78	0218-3C	1208 Low Pressure Steam Dump	Valve does not stroke fully	Remove internals. Removed scoring by stonning. Reinstalled
8-23-78	0239-02	Containment Ventilation	Duct inspection cover	Fabricated plate, drilled holes, welded handles and installed using red rubber gasket
-15-78	0241-3C	250A Chemical & Volume Con- trol system	Isolation valve needs internal inspection and check internals when shut	Inspected. Lapped seat to body and replaced
-23-78	2043-03	Hydraulic Snubber Removal	Remove pins	Remove restraint for testing program
-18-78	0244-02	#32 Charging Pump CVCS	Inspect pump plungers shaft seals	Inspected and Repaired
19-78	0250-02	#32 ABFP	Valve #1310B will not close	Disassembled and cleaned. Reassembled and adjusted stroke
-29-78	0253 <b>-</b> 3C	Fan Coolant Units Cont. Bldg	New Charcoal Beds for #31, #32 33, 34, & 35	Removed charcoal from #31 and 33 Tested - OK
-5-78	0254-3C	456 Pressurizer Relief Valve	Leaks	Found cuts, replaced valve internals
-4-78	0261-02	#33 CVCS	Repack piston plunger on #33 Charging Pump	Replaced all parts
-14-78	0263-3B	SWN-42 Relief Valve on #33 Fan Cooler Unit	Leaks	Seating surfaces damaged. Disassembled and lapped. Seal relief press reinstalled

## MONTHLY MAINTENANCE REPORT

:

:

August 1978

				Month
DATE -	W.R. #	EQUIPMENT	MALFUNCTION	CORRECTIVE ACTION
9-15-78	0264-3D	#31 Steam Generator	Open up primary waterboxes, eddy current inspection of tubes	Removed manways. Eddy current testin and explosive tube plugging performed
-15-78	0266-02	Service Water	3" drain heater leaks	Repaired
-15-78	0269-3C	#32 CVCS	Inspect #32 charging pump valve	Disassembled. Installed new nozzle and disc pressure tested valve and installed
-29-78	0270-1A	#32 RHR pump	Excessive Seal Leakage	Replaced damaged gasket and Mechanical Seal. Installed pump and motor
-18-78	0271-3C	Hydraulic Snubber Lower #31 Steam Generator	Inspect fittings for leaks	Tightened two leaking fittings
-6-78	0277-02	#32 CVCS	Repack #32 charging pump	Repacked
-29-78	0051-3C 0061-3D	Press ray seal Part length control rods	Remove from reactor core	Removed part length rods
-29-78	0112-3C	Safeguard System	Install replacement valves	Replace 10 SWN valves in PAB
-22-78	0113-02	Rod Monitoring	Repair sample line from FCU	Repaired with new spool pieces
-15-78	0156-3C	cvcs	Boric Acid Flow Transmitter	Removed and installed new transmitter