DK Central File



## UNITED STATES ATOMIC ENERGY COMMISSION DIRECTORATE OF REGULATORY OPERATION REGION 1

## 970 BROAD STREET NEWARK, NEW-JERSEY-07402

631 Park Avenue King of Prussia, Pennsylvania 19406 September 18, 1973

Consolidated Edison Company
Attention: Mr. W. E. Caldwell, Jr.
Executive Vice-President
4 Irving Place
New York, New York 10003

Docket No. 50-286

## Gentlemen:

This refers to the inspection conducted by Mr. Fasano of this office on August 28-30, 1973 of activities authorized under AEC License No. CPPR-62 and to the discussions of our findings held by Mr. Fasano of this office, with Mr. Cantone and Mr. Whittier on August 30, 1973.

Areas examined during this inspection are described in the Regulatory Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures, and representative records, interviews with plant personnel and observations by the inspector.

Within the scope of this inspection no violations or safety items were observed.

In accordance with Section 2.790 of the AEC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Eldon J. Brunner, Chief

Facility Test and Startup Branch

Enclosure:

RO Inspection Report No. 50-286/73-8

bcc: RO Chief, FS&EB, HQ

RO: HQ(4)

RO Files

Central Mail and Files

GC

Directorate of Licensing (4)

PDR .

Local PDR

NSIC

DTIE

State of New York