

ENCLOSURE

Description of Noncompliance Item

Consolidated Edison Company of New York
Docket No. 50-286
License No. CPPR-62

The following item appears to be in noncompliance with Appendix B, 10 CFR 50, as identified below:

Criterion VIII, "Identification and Control of Materials, Parts, and Components", Appendix B, 10 CFR 50, states in part, "Measures shall be established for the identification and control of materials, parts, and components . . . These measures shall assure that identification of the item is maintained by heat number, part number, serial number or other appropriate means . . . as required throughout fabrication, erection, installation, and use of the item . . ."

Contrary to the above, the inspector found that the welding electrode control program had been changed to delete the requirement for recording of heat numbers on the field weld record. In addition, no records were available to indicate traceability of welding electrodes used in the field welding of the reactor coolant piping.

811190933 720301
PDR ADOCK 05000286
Q PDR