

Central files

UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19306

AUG 14 1974

License No. CPPR-62
Docket No. 50-286
Inspection No. 50-286/74-13

Consolidated Edison Company of
New York, Inc.
Attention: Mr. W. J. Cahill, Jr.
Vice President
4 Irving Place
New York, New York 10003

Gentlemen:

This refers to the inspection conducted by Mr. Folsom of this office on August 5-7, 1974 at Buchanan, New York of activities authorized by AEC License No. CPPR-62 and to the discussions of our findings held by Mr. Folsom with Dr. Coulbourn of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Regulatory Operations Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or safety items were observed.

In accordance with Section 2.790 of the AEC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

8111110459 740814
PDR ADOCK 05000286
Q PDR

Bj

Consolidated Edison Company of
New York, Inc.

-2-

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Robert T. Carlson, Chief
Facility Construction and Engineering
Support Branch

Enclosure:

RO Inspection Report No. 50-286/74-13

cc: A. D. Kohler, Jr., Resident Construction Engineer
A. E. Upton, Esquire

bcc: (W/encls)

RO Chief, FS&EB

RO:HQ (5)

DL (4 w/encls; plus 9 cyps of report)

DR Central Files

RS (3)

PDR

Local PDR

RO Files

NSIC

DTIE

State of New York

OGC

Reg Reg Reading Room