

APPENDIX A
NOTICE OF VIOLATION

New York Power Authority
Indian Point 3 Nuclear Power Plant

Docket No. 50-286
License No. DPR-64

As a result of the inspection conducted on September 29, 1987 to November 10, 1987, and in accordance with the General Statement of Policy and Procedure for NRC Enforcement Actions, 10 CFR, Part 2, Appendix C, the following violation was identified:

10 CFR 50.73(b)(2)(ii)(J)(2) concerning the Licensee Event Reporting (LER) system states that the licensee shall discuss the details of any event caused by a personnel error. In particular, the discussion must include the cause of the personnel error (cognitive or procedural), the details of any procedural errors, any unusual characteristics of the work location that may have contributed to the error, and the type of personnel involved.

Contrary to the above, the licensee failed to include the cause of the personnel error (cognitive or procedural), the details of any procedural errors, any unusual characteristics of the work location that may have contributed to the error, and the type of personnel involved in LER 87-10 which detailed a reactor trip and safety injection caused by a personnel error. Similar deficiencies also existed in the description of personnel errors associated with LERs 87-08, 86-04, and 86-02.

This is Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, the New York Power Authority is hereby required to submit to this office within thirty days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8712010241 871123
PDR ADDCK 05000286
Q PDR

OFFICIAL RECORD COPY

IR IP3 87-24 - 0003.0.0
11/20/87