

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Trijicon, Inc.		2. NRC/REGIONAL OFFICE Region III	
REPORT NUMBER(S) 2010-01		2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-19451	4. LICENSE NUMBER(S) 21-19874-01	5. DATE(S) OF INSPECTION January 22, 2010	
6. INSPECTION PROCEDURES USED 87126 (9/28/2005)		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03214	2. PRIORITY 5	3. LICENSEE CONTACT Darin Schick, Chief Engineer	4. TELEPHONE NUMBER 248-960-7700
------------------------------------	-------------------------	--	--

Main Office Inspection Next Inspection Date: **January 2015**

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is a manufacturing and distribution business authorized by the license for possession of hydrogen-3 incident to the manufacture of gunsites and for research and development as indicated in the license. Licensed material is received and used as sealed light sources which have been evaluated and documented in the sealed sources and devices registry.

Performance Observations

During the inspection, the licensee's staff demonstrated/discussed: (1) inventory and license activity limits; (2) contamination surveys; (3) package transfers and shipping procedures; (4) receipt, storage and security of licensed material; (5) employee training; (6) waste handling procedures; and (7) emergency procedures and postings for contamination events.